

CENTTECH®

Digital Postal Scale

Item 95069

INSTRUCTIONS AND PRECAUTIONS



Visit our website at:
<http://www.harborfreight.com>

⚠ WARNING

**Read this material before using this product.
Failure to do so can result in serious injury.
SAVE THIS MANUAL.**

**When unpacking, make sure that the product is intact and undamaged.
If any parts are missing or broken, please call
1-800-444-3353 as soon as possible.**

Copyright© 2006 by Harbor Freight Tools®. All rights reserved. No portion of this document or any artwork contained herein may be reproduced in any shape or form without the express written consent of Harbor Freight Tools. Diagrams within this document may not be drawn proportionally. Due to continuing improvements, actual product may differ slightly from the product described herein. Tools required for assembly and service may not be included.

**For technical questions or replacement parts, please call 1-800-444-3353.
Email our tech support at: tech@harborfreight.com**

Specifications

Max. Capacity	70 LB. / 32 kg
Measurements	Pounds / Kilograms
Shut-Off	90-second auto shut-off
Power Source	120V~, 60Hz / 9VDC, 100mA Adaptor (included) 9V Battery (not included)

NOTE: Do not use scale for commerce or trade.

Important Safety Information

1. Do not exceed Scale's 70 LB. / 32 kg max. weight capacity. "ERR" will appear on digital display if scale is overloaded.
2. Position battery in proper polarity.
3. This product is not a toy. Do not allow children to play with or near this item.
4. Weight readings are for household use only. Do not use for commerce or trade.
5. Inspect before every use; do not use if parts are loose or damaged.

Setup Instructions



Read the **ENTIRE IMPORTANT SAFETY INFORMATION** section at the beginning of this document including all text under subheadings therein before set up or use of this product.

Note: Place Scale in sheltered area when in use as air movement and breathing on Scale will affect accuracy.

Installing/Replacing Battery

1. The Battery must be replaced if a battery icon is displayed in the LCD window. Gently push in on the tab on the battery cover and pull the battery cover up.
2. Unplug the battery connector from the battery. Replace the dead battery with a new 9V battery.
3. Snap the battery connection back onto the top of the battery.

Using Adaptor

1. Plug the Adaptor plug into the Adaptor jack located on the Scale. Plug the Adaptor into a 120V electrical outlet.
2. When done using Scale, unplug the Adaptor plug from Digital Scale. Unplug the Adaptor from electrical outlet.

Operation

1. Press the Mode button to set the Scale to the desired unit of weight, either pounds or kilograms.
2. Set the Scale on a level surface free from vibration and clear of electronic interference such as radios, phones and microwaves.
3. Press the On/Off button to turn ON the Scale.
4. Wait until the LCD readout displays "0.0".
5. Place the object on the weighing platform. Always place objects on platform gently. Wait for the LCD readout to indicate the weight of the item.
6. Press the Hold button to keep the weight displayed on the readout.
3. Wait for the weight to be displayed. The weight shown will be for the item only.
4. After this operation, a series of dotted lines may appear on the readout.
5. To clear Tare mode, remove the items from the weighing platform and turn the Scale OFF. Turn the Scale back ON to continue weighing.

Inspection, Maintenance and Cleaning

1. Always unplug the Digital Scale from its electrical outlet before performing any inspection, maintenance, or cleaning.
2. Clean with a soft cloth as necessary.
3. **CAUTION!** Do not submerge the Digital Scale in liquid.

Note: Replacement parts are not available.

Weighing Tare

Note: Tare is the deduction of the container weight from the total (gross) weight. It assists in determining net weight (weight of contents excluding container).

1. Press the ON/OFF button. Place the container onto the Scale's weighing platform.
2. Press the Tare button and wait several seconds until "0" is displayed. Once the "0" is displayed, release the Tare button and put the item that you want weighed (apart from the container) on the scale along with the container which you already have on the Scale.

Limited 90 Day Warranty

Harbor Freight Tools Co. makes every effort to assure that its products meet high quality and durability standards, and warrants to the original purchaser that this product is free from defects in materials and workmanship for the period of 90 days from the date of purchase. This warranty does not apply to damage due directly or indirectly, to misuse, abuse, negligence or accidents, repairs or alterations outside our facilities, criminal activity, improper installation, normal wear and tear, or to lack of maintenance. We shall in no event be liable for death, injuries to persons or property, or for incidental, contingent, special or consequential damages arising from the use of our product. Some states do not allow the exclusion or limitation of incidental or consequential damages, so the above limitation of exclusion may not apply to you. THIS WARRANTY IS EXPRESSLY IN LIEU OF ALL OTHER WARRANTIES, EXPRESS OR IMPLIED, INCLUDING THE WARRANTIES OF MERCHANTABILITY AND FITNESS.

To take advantage of this warranty, the product or part must be returned to us with transportation charges prepaid. Proof of purchase date and an explanation of the complaint must accompany the merchandise. If our inspection verifies the defect, we will either repair or replace the product at our election or we may elect to refund the purchase price if we cannot readily and quickly provide you with a replacement. We will return repaired products at our expense, but if we determine there is no defect, or that the defect resulted from causes not within the scope of our warranty, then you must bear the cost of returning the product.

This warranty gives you specific legal rights and you may also have other rights which vary from state to state.

Record Serial Number Here:

Note: If product has no serial number, record month and year of purchase instead.

CEN-TECH

3491 Mission Oaks Blvd. • PO Box 6009 • Camarillo, CA 93011 • (800) 444-3353